

Port of Boston Notice to Mariners 006. 2016

Dated 13.04.16

Change to Freeman Inner Buoy

Further to Local Notice to Mariners 002.16

Mariners are advised that the West Cardinal Mark, Freeman Inner Buoy, Position 52 58.56N 000 11.42E has now been removed from station.

It has been replaced by a starboard hand lateral mark with green topmark, flash characteristic Fl. Green every 6 seconds. The buoy has been renamed No. 7.

The Buoy has been laid in position 52 58.628N 000 11 405E.

Captain Richard Walker
Harbour Master
Port of Boston Ltd

01205 365571
harbourmaster@portofboston.co.uk